

Synchronous Machine

① Armature

- It is a three phase winding placed in the stator.
- The three phase armature windings are placed 120° (electrical) apart in space.
- Stator iron is built up of thin laminations to reduce eddy current loss.

② Field

- Field winding is placed in the rotor and requires DC.

There are two types of rotor.

① Cylindrical Poles

② Salient Poles




Figure: Schematic diagram of a 3 – ϕ synchronous machine

The synchronous speed is

$$N_s = \frac{120f}{P}$$

where N_s is in rpm, f is the frequency in Hz and P is the number of poles.

The relationship between the electrical angle (θ) and the mechanical angle (θ_m) is

$$\theta = \frac{P}{2}\theta_m$$

In a 2-pole machine,

$$\theta = \theta_m$$

Assumptions made in modelling.

- 1 Stator windings are distributed sinusoidally along the air gap.
- 2 Stator slots do not cause any variation in the rotor inductances.
- 3 Magnetic hysteresis is negligible.
- 4 Magnetic circuit is considered as linear.

The following convention is used.

- 1 q -axis is leading d -axis.
- 2 Two amortisseur in q -axis and one in d -axis are used. Hence 2 windings (including the field winding) in d -axis and 2 windings in q -axis.




Figure: Stator and Rotor windings of a synchronous machine

Voltage Equations

The stator voltage equations are

$$v_a = -i_a r_s + \frac{d\lambda_a}{dt} \quad (1)$$

$$v_b = -i_b r_s + \frac{d\lambda_b}{dt} \quad (2)$$

$$v_c = -i_c r_s + \frac{d\lambda_c}{dt} \quad (3)$$

where

v_a, v_b, v_c = instantaneous stator phase to neutral voltage

i_a, i_b, i_c = instantaneous stator currents in phases a,b,c

r_s = stator resistance per phase

$\lambda_a, \lambda_b, \lambda_c$ = flux linkages in phases a,b,c

The rotor circuit voltage equations are

$$v_{fd} = i_{fd}r_{fd} + \frac{d\lambda_{fd}}{dt} \quad (4)$$

$$v_{1d} = i_{1d}r_{1d} + \frac{d\lambda_{1d}}{dt} \quad (5)$$

$$v_{1q} = i_{1q}r_{1q} + \frac{d\lambda_{1q}}{dt} \quad (6)$$

$$v_{2q} = i_{2q}r_{2q} + \frac{d\lambda_{2q}}{dt} \quad (7)$$

$v_{fd}, v_{1d}, v_{1q}, v_{2q}$ = rotor field, 1d, 1q, 2q voltages

$i_{fd}, i_{1d}, i_{1q}, i_{2q}$ = rotor field, 1d, 1q, 2q currents

$r_{fd}, r_{1d}, r_{1q}, r_{2q}$ = rotor field, 1d, 1q, 2q resistances

$\lambda_{fd}, \lambda_{1d}, \lambda_{1q}, \lambda_{2q}$ = rotor field, 1d, 1q, 2q flux linkages

Flux Linkage Equations

The flux linkages in the phase a , b and c windings are

$$\begin{aligned}\lambda_a &= -l_{aa}i_a - l_{ab}i_b - l_{ac}i_c + l_{afd}i_{fd} + l_{a1d}i_{1d} + l_{a1q}i_{1q} + l_{a2q}i_{2q} \\ \lambda_b &= -l_{ba}i_a - l_{bb}i_b - l_{bc}i_c + l_{bfd}i_{fd} + l_{b1d}i_{1d} + l_{b1q}i_{1q} + l_{b2q}i_{2q} \\ \lambda_c &= -l_{ca}i_a - l_{cb}i_b - l_{cc}i_c + l_{cfd}i_{fd} + l_{c1d}i_{1d} + l_{c1q}i_{1q} + l_{c2q}i_{2q}\end{aligned}$$

The negative sign in the stator currents is due to their direction.
In matrix form,

$$\begin{bmatrix} \lambda_a \\ \lambda_b \\ \lambda_c \end{bmatrix} = - \begin{bmatrix} l_{aa} & l_{ab} & l_{ac} \\ l_{ab} & l_{bb} & l_{bc} \\ l_{ac} & l_{bc} & l_{cc} \end{bmatrix} \begin{bmatrix} i_a \\ i_b \\ i_c \end{bmatrix} + \begin{bmatrix} l_{afd} & l_{a1d} & l_{a1q} & l_{a2q} \\ l_{bfd} & l_{b1d} & l_{b1q} & l_{b2q} \\ l_{cfd} & l_{c1d} & l_{c1q} & l_{c2q} \end{bmatrix} \begin{bmatrix} i_{fd} \\ i_{1d} \\ i_{1q} \\ i_{2q} \end{bmatrix} \quad (8)$$

$$\lambda_{abc} = -L_{ss}i_{abc} + L_{sr}i_r$$

The rotor circuit flux linkages can be written as


$$\begin{bmatrix} \lambda_{fd} \\ \lambda_{1d} \\ \lambda_{1q} \\ \lambda_{2q} \end{bmatrix} = - \begin{bmatrix} l_{fda} & l_{fdb} & l_{fdc} \\ l_{1da} & l_{1db} & l_{1dc} \\ l_{1qa} & l_{1qb} & l_{1qc} \\ l_{2qa} & l_{2qb} & l_{2qc} \end{bmatrix} \begin{bmatrix} i_a \\ i_b \\ i_c \end{bmatrix} + \begin{bmatrix} l_{fdfd} & l_{fd1d} & 0 & 0 \\ l_{1dfd} & l_{1d1d} & 0 & 0 \\ 0 & 0 & l_{1q1q} & l_{1q2q} \\ 0 & 0 & l_{2q1q} & l_{2q2q} \end{bmatrix} \begin{bmatrix} i_{fd} \\ i_{1d} \\ i_{1q} \\ i_{2q} \end{bmatrix} \quad (9)$$

The mutual inductance between the d -axis windings and the q -axis windings is zero as their fluxes are in quadrature.

$$\lambda_r = -L_{rs}i_{abc} + L_{rr}i_r$$

L_{ss} , L_{sr} and L_{rs} depend on θ .

The permeance varies with θ .



$$P = P_{avg} + P_p \cos(2\theta)$$





Figure: Phase a mmf

Stator Self Inductances

peak $MMF_a = N_a i_a$

peak $MMF_{ad} = N_a i_a \cos \theta$

peak $MMF_{aq} = N_a i_a \cos(\theta + 90^\circ) = -N_a i_a \sin \theta$



The fluxes along d and q axes are

$$\phi_{ad} = N_a i_a \cos \theta P_d$$

$$\phi_{aq} = -N_a i_a \sin \theta P_q$$

The flux along the axis a is given by

$$\phi_{aa} = \phi_{ad} \cos \theta - \phi_{aq} \sin \theta$$

$$\phi_{aa} = N_a i_a P_d \cos^2 \theta + N_a i_a P_q \sin^2 \theta$$

$$\phi_{aa} = N_a i_a \left(P_d \left(\frac{1 + \cos 2\theta}{2} \right) + P_q \left(\frac{1 - \cos 2\theta}{2} \right) \right)$$

$$\phi_{aa} = N_a i_a \left(\frac{P_d + P_q}{2} + \frac{P_d - P_q}{2} \cos 2\theta \right)$$

The self inductance l_{aa} is

$$l_{aa} = \frac{N_a \phi_{aa}}{i_a} = N_a^2 \left(\frac{P_d + P_q}{2} \right) + N_a^2 \left(\frac{P_d - P_q}{2} \cos 2\theta \right)$$

This can be written as

$$l_{aa} = l_{aa0} + l_{aap} \cos 2\theta \quad (10)$$

where $l_{aa0} = N_a^2 \left(\frac{P_d + P_q}{2} \right)$ and $l_{aap} = N_a^2 \left(\frac{P_d - P_q}{2} \right)$ Since the windings of phases b and c are identical to a and are displaced from it by 120° and 240° , respectively,

$$l_{bb} = l_{aa0} + l_{aap} \cos 2(\theta - 120^\circ) = l_{aa0} + l_{aap} \cos(2\theta + 120^\circ) \quad (11)$$

$$l_{cc} = l_{aa0} + l_{aap} \cos 2(\theta - 240^\circ) = l_{aa0} + l_{aap} \cos(2\theta - 120^\circ) \quad (12)$$

Stator Mutual Inductances

The flux linking phase a due to mmf of phase b is

$$\phi_{ba} = \phi_{bd} \cos \theta - \phi_{bq} \sin \theta$$

$$\phi_{ba} = N_b i_b P_d \cos(\theta - 120^\circ) \cos \theta + N_b i_b P_q \sin(\theta - 120^\circ) \sin \theta$$

$$\phi_{ba} = N_b i_b \left[\left(\frac{P_d}{2} (\cos(2\theta - 120^\circ) + \cos(120^\circ)) + \frac{P_q}{2} (\cos(120^\circ) - \cos(2\theta - 120^\circ)) \right) \right]$$

$$\phi_{ba} = N_b i_b \left(-\frac{P_d + P_q}{4} + \frac{P_d - P_q}{2} (\cos(2\theta - 120^\circ)) \right)$$

The flux linkage of phase a due to current i_b is

$$\lambda_{ba} = N_a \phi_{ba} = N_a N_b i_b \left(-\frac{P_d + P_q}{4} + \frac{P_d - P_q}{2} (\cos(2\theta - 120^\circ)) \right)$$

Since $N_a = N_b$, the mutual inductance between a and b is

$$l_{ba} = \frac{N_a \phi_{ba}}{i_b} = N_a^2 \left(-\frac{P_d + P_q}{4} + \frac{P_d - P_q}{2} (\cos(2\theta - 120^\circ)) \right)$$
$$l_{ba} = l_{ab} = -\frac{1}{2} l_{aa0} + l_{aap} \cos(2\theta - 120^\circ)$$
$$= -\frac{1}{2} l_{aa0} - l_{aap} \cos(2\theta + 60^\circ) \quad (13)$$

Similarly,

$$l_{ca} = l_{ac} = -\frac{1}{2} l_{aa0} - l_{aap} \cos(2\theta - 60^\circ) \quad (14)$$

$$l_{bc} = l_{cb} = -\frac{1}{2} l_{aa0} - l_{aap} \cos(2\theta - 180^\circ) \quad (15)$$

$$\mathbf{L}_{ss} = \begin{bmatrix} I_{aa0} + I_{aap} \cos 2\theta & -\frac{1}{2} I_{aa0} - I_{aap} \cos(2\theta + 60^\circ) & -\frac{1}{2} I_{aa0} - I_{aap} \cos(2\theta - 60^\circ) \\ -\frac{1}{2} I_{aa0} - I_{aap} \cos(2\theta + 60^\circ) & I_{aa0} + I_{aap} \cos(2\theta + 120^\circ) & -\frac{1}{2} I_{aa0} - I_{aap} \cos(2\theta - 180^\circ) \\ -\frac{1}{2} I_{aa0} - I_{aap} \cos(2\theta - 60^\circ) & -\frac{1}{2} I_{aa0} - I_{aap} \cos(2\theta - 180^\circ) & I_{aa0} + I_{aap} \cos(2\theta - 120^\circ) \end{bmatrix} \quad (16)$$

Mutual inductances between stator and rotor

Since the rotor windings see a constant permeance,

$$\mathbf{L}_{sr} = \begin{bmatrix} l_{afd} \cos \theta & l_{a1d} \cos \theta & -l_{a1q} \sin \theta & -l_{a2q} \sin \theta \\ l_{bfd} \cos(\theta - 120^\circ) & l_{b1d} \cos(\theta - 120^\circ) & -l_{b1q} \sin(\theta - 120^\circ) & -l_{b2q} \sin(\theta - 120^\circ) \\ l_{cfd} \cos(\theta + 120^\circ) & l_{c1d} \cos(\theta + 120^\circ) & -l_{c1q} \sin(\theta + 120^\circ) & -l_{c2q} \sin(\theta + 120^\circ) \end{bmatrix} \quad (17)$$

Let

$$l_{afd} = l_{bfd} = l_{cfd} = l_{sfd}$$

$$l_{a1d} = l_{b1d} = l_{c1d} = l_{s1d}$$

$$l_{a1q} = l_{b1q} = l_{c1q} = l_{s2q}$$

$$l_{a2q} = l_{b2q} = l_{c2q} = l_{s2q}$$

$$\mathbf{L}_{sr} = \begin{bmatrix} l_{sfd} \cos \theta & l_{s1d} \cos \theta & -l_{s1q} \sin \theta & -l_{s2q} \sin \theta \\ l_{sfd} \cos(\theta - 120^\circ) & l_{s1d} \cos(\theta - 120^\circ) & -l_{s1q} \sin(\theta - 120^\circ) & -l_{s2q} \sin(\theta - 120^\circ) \\ l_{sfd} \cos(\theta + 120^\circ) & l_{s1d} \cos(\theta + 120^\circ) & -l_{s1q} \sin(\theta + 120^\circ) & -l_{s2q} \sin(\theta + 120^\circ) \end{bmatrix} \quad (18)$$

- L_{ss} , L_{sr} and L_{rs} vary with angle θ which in turn varies with time.
- This introduces complexity in solving problems.
- Therefore, a suitable transformation is required.
- $dq0$ transformation is used to transform the stator variables into new variables.

dq0 Transformation

The transformation matrix is

$$T_{dq0} = k_1 \begin{bmatrix} \cos \theta & \cos(\theta - 120^\circ) & \cos(\theta + 120^\circ) \\ -\sin \theta & -\sin(\theta - 120^\circ) & -\sin(\theta + 120^\circ) \\ k_2 & k_2 & k_2 \end{bmatrix} \quad (19)$$

- It is also called Park's Transformation.
- The constants k_1 and k_2 are arbitrary.
- In most of the literature, $k_1 = \frac{2}{3}$ and $k_2 = \frac{1}{2}$ are used.
- $k_1 = \sqrt{\frac{2}{3}}$ and $k_2 = \frac{1}{\sqrt{2}}$ are also used in some literature.
- In this course, $k_1 = \frac{2}{3}$ and $k_2 = \frac{1}{2}$ are used.

Let us apply the $dq0$ transformation to stator currents.

$$\begin{aligned}i_a &= I_m \cos(\omega t) \\i_b &= I_m \cos(\omega t - 120^\circ) \\i_c &= I_m \cos(\omega t + 120^\circ)\end{aligned}$$

$$\begin{bmatrix} i_d \\ i_q \\ i_0 \end{bmatrix} = T_{dq0} \begin{bmatrix} i_a \\ i_b \\ i_c \end{bmatrix} \quad (20)$$

$$\begin{bmatrix} i_d \\ i_q \\ i_0 \end{bmatrix} = \frac{2}{3} \begin{bmatrix} \cos \theta & \cos(\theta - 120^\circ) & \cos(\theta + 120^\circ) \\ -\sin \theta & -\sin(\theta - 120^\circ) & -\sin(\theta + 120^\circ) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix} \begin{bmatrix} I_m \cos \omega t \\ I_m \cos(\omega t - 120^\circ) \\ I_m \cos(\omega t + 120^\circ) \end{bmatrix}$$
$$\begin{bmatrix} i_d \\ i_q \\ i_0 \end{bmatrix} = \begin{bmatrix} I_m \cos(\omega t - \theta) \\ I_m \sin(\omega t - \theta) \\ 0 \end{bmatrix} \quad (21)$$

If θ is measured with respect to the synchronously rotating reference,

$$\theta = \omega t + \delta$$

$$\begin{bmatrix} i_d \\ i_q \\ i_0 \end{bmatrix} = \begin{bmatrix} I_m \cos \delta \\ -I_m \sin \delta \\ 0 \end{bmatrix} \quad (22)$$

For balanced steady state operation, i_d and i_q are constant.

$$i_0 = \frac{1}{3}(i_a + i_b + i_c) = 0$$

- Since $k_1 = \frac{2}{3}$ and $k_2 = \frac{1}{2}$, the peak value of i_d and i_q is the same as the peak value of the stator current.
- Two fictitious windings carrying current i_d and i_q rotating at synchronous speed produce the same effect as that of three phase stator windings.

The inverse transformation is

$$\mathbf{T}_{dq0}^{-1} = \begin{bmatrix} \cos \theta & -\sin \theta & 1 \\ \cos(\theta - 120^\circ) & -\sin(\theta - 120^\circ) & 1 \\ \cos(\theta + 120^\circ) & -\sin(\theta + 120^\circ) & 1 \end{bmatrix} \quad (23)$$

$$v_{dq0} = \mathbf{T}_{dq0} v_{abc}; \quad i_{dq0} = \mathbf{T}_{dq0} i_{abc}$$

$$v_{abc} = \mathbf{T}_{dq0}^{-1} v_{dq0}; \quad i_{abc} = \mathbf{T}_{dq0}^{-1} i_{dq0}$$

Let us apply the $dq0$ transformation to the instantaneous power.

$$s = \begin{bmatrix} v_a \\ v_b \\ v_c \end{bmatrix}^T \begin{bmatrix} i_a \\ i_b \\ i_c \end{bmatrix} = \left(\mathbf{T}_{dq0}^{-1} \begin{bmatrix} v_d \\ v_q \\ v_0 \end{bmatrix} \right)^T \left(\mathbf{T}_{dq0}^{-1} \begin{bmatrix} i_d \\ i_q \\ i_0 \end{bmatrix} \right) \quad (24)$$

$$s = \begin{bmatrix} v_d \\ v_q \\ v_0 \end{bmatrix}^T (\mathbf{T}_{dq0}^{-1})^T \mathbf{T}_{dq0}^{-1} \begin{bmatrix} i_d \\ i_q \\ i_0 \end{bmatrix}$$

$$s = \begin{bmatrix} v_d \\ v_q \\ v_0 \end{bmatrix}^T \begin{bmatrix} \frac{3}{2} & 0 & 0 \\ 0 & \frac{3}{2} & 0 \\ 0 & 0 & 3 \end{bmatrix} \begin{bmatrix} i_d \\ i_q \\ i_0 \end{bmatrix}$$

$$s = v_a i_a + v_b i_b + v_c i_c = \frac{3}{2}(v_d i_d + v_q i_q + 2v_0 i_0) \quad (25)$$

The transformation is not power invariant.

$$v_a i_a + v_b i_b + v_c i_c \neq v_d i_d + v_q i_q + v_0 i_0$$

If $k_1 = \sqrt{\frac{2}{3}}$ and $k_2 = \frac{1}{\sqrt{2}}$, the transformation will be power invariant.

Let us apply the $dq0$ transformation to stator voltages.

$$\begin{bmatrix} v_d \\ v_q \\ v_0 \end{bmatrix} = -T_{dq0} \begin{bmatrix} r_s & 0 & 0 \\ 0 & r_s & 0 \\ 0 & 0 & r_s \end{bmatrix} T_{dq0}^{-1} \begin{bmatrix} i_d \\ i_q \\ i_0 \end{bmatrix} \\ + T_{dq0} \frac{d}{dt} \left(T_{dq0}^{-1} \begin{bmatrix} \lambda_d \\ \lambda_q \\ \lambda_0 \end{bmatrix} \right)$$

$$\begin{bmatrix} v_d \\ v_q \\ v_0 \end{bmatrix} = -T_{dq0} \begin{bmatrix} r_s & 0 & 0 \\ 0 & r_s & 0 \\ 0 & 0 & r_s \end{bmatrix} T_{dq0}^{-1} \begin{bmatrix} i_d \\ i_q \\ i_0 \end{bmatrix} \\ + T_{dq0} T_{dq0}^{-1} \frac{d}{dt} \left(\begin{bmatrix} \lambda_d \\ \lambda_q \\ \lambda_0 \end{bmatrix} \right) \\ + T_{dq0} \frac{d}{dt} \left(T_{dq0}^{-1} \right) \begin{bmatrix} \lambda_d \\ \lambda_q \\ \lambda_0 \end{bmatrix}$$

$$\begin{bmatrix} v_d \\ v_q \\ v_0 \end{bmatrix} = - \begin{bmatrix} r_s & 0 & 0 \\ 0 & r_s & 0 \\ 0 & 0 & r_s \end{bmatrix} \begin{bmatrix} i_d \\ i_q \\ i_0 \end{bmatrix} + \begin{bmatrix} 0 & -\omega & 0 \\ \omega & 0 & 0 \\ 0 & 0 & 0 \end{bmatrix} \begin{bmatrix} \lambda_d \\ \lambda_q \\ \lambda_0 \end{bmatrix} + \frac{d}{dt} \left(\begin{bmatrix} \lambda_d \\ \lambda_q \\ \lambda_0 \end{bmatrix} \right)$$

The stator and rotor voltage equations are as follows:

$$v_d = -r_s i_d - \omega \lambda_q + \frac{d\lambda_d}{dt} \quad (26)$$

$$v_q = -r_s i_q + \omega \lambda_d + \frac{d\lambda_q}{dt} \quad (27)$$

$$v_0 = -r_s i_0 + \frac{d\lambda_0}{dt} \quad (28)$$

$$v_{fd} = r_{fd} i_{fd} + \frac{d\lambda_{fd}}{dt} \quad (29)$$

$$v_{1d} = r_{1d} i_{1d} + \frac{d\lambda_{1d}}{dt} \quad (30)$$

$$v_{1q} = r_{1q} i_{1q} + \frac{d\lambda_{1q}}{dt} \quad (31)$$

$$v_{2q} = r_{2q} i_{2q} + \frac{d\lambda_{2q}}{dt} \quad (32)$$

Applying the $dq0$ transformation to the stator flux equations.

$$\begin{bmatrix} \lambda_d \\ \lambda_q \\ \lambda_0 \end{bmatrix} = -T_{dq0} L_{ss} T_{dq0}^{-1} \begin{bmatrix} i_d \\ i_q \\ i_0 \end{bmatrix} + T_{dq0} L_{sr} \begin{bmatrix} i_{fd} \\ i_{1d} \\ i_{1q} \\ i_{2q} \end{bmatrix} \quad (34)$$

After simplification,

$$\begin{bmatrix} \lambda_d \\ \lambda_q \\ \lambda_0 \end{bmatrix} = - \begin{bmatrix} \frac{3}{2}(l_{aa0} + l_{aap}) & 0 & 0 \\ 0 & \frac{3}{2}(l_{aa0} - l_{aap}) & 0 \\ 0 & 0 & l_{aa0} \end{bmatrix} \begin{bmatrix} i_d \\ i_q \\ i_0 \end{bmatrix} + \begin{bmatrix} l_{sfd} & l_{s1d} & 0 & 0 \\ 0 & 0 & l_{s1q} & l_{s2q} \\ 0 & 0 & 0 & 0 \end{bmatrix} \begin{bmatrix} i_{fd} \\ i_{1d} \\ i_{1q} \\ i_{2q} \end{bmatrix} \quad (35)$$

Let us define the following.

$$l_d = \frac{3}{2}(l_{aa0} + l_{aap}); \quad l_q = \frac{3}{2}(l_{aa0} - l_{aap})$$

where l_d , l_q are the inductances along d , q -axis corresponding to the total flux linkage.

$$l_d = l_{md} + l_{ls}; \quad l_q = l_{mq} + l_{ls}$$

where

l_{md} = the mutual inductance along d

l_{mq} = the mutual inductance along q

l_{ls} = leakage inductance

$$\lambda_d = -(l_{md} + l_{ls})i_d + l_{sfd}i_{fd} + l_{s1d}i_{1d} \quad (36)$$

$$\lambda_q = -(l_{mq} + l_{ls})i_q + l_{s1q}i_{1q} + l_{s2q}i_{2q} \quad (37)$$

$$\lambda_0 = -l_{ls}i_0 \quad (38)$$

$$\lambda_{fd} = -\frac{3}{2}l_{sfd}i_d + l_{fdfd}i_{fd} + l_{fd1d}i_{1d} \quad (39)$$

$$\lambda_{1d} = -\frac{3}{2}l_{s1d}i_d + l_{fd1d}i_{fd} + l_{1d1d}i_{1d} \quad (40)$$

$$\lambda_{1q} = -\frac{3}{2}l_{s1q}i_q + l_{1q1q}i_{1q} + l_{1q2q}i_{2q} \quad (41)$$

$$\lambda_{2q} = -\frac{3}{2}l_{s2q}i_q + l_{1q2q}i_{1q} + l_{2q2q}i_{2q} \quad (42)$$

$$(43)$$

Advantages of $dq0$ transformation

- ① The dynamic performance equations have constant inductances.
- ② For balanced conditions, zero sequence quantities disappear.
- ③ For balanced steady state operation, the stator quantities have constant values. For other modes of operation, they vary with time. Stability studies involve slow variations having frequencies below 2 to 3 Hz.
- ④ The d and q -axed parameters may be directly measured from tests.

Per unit representation

- The $dq0$ transformation converts inductances into constants irrespective of angle θ .
- However, the mutual inductances between the stator windings and the rotor windings are not equal.
- To make them equal, a proper per unit system should be chosen.
- This will minimize computational complexity.

Base Quantities for Stator Variables

Let us define the following.

$$\begin{aligned}V_{base} &= V_{rms}(1 - n) \text{ kV} \\S_{base} &= 3V_{base}I_{base} = \text{three phase rated MVA} \\I_{base} &= \frac{S_{base}}{3V_{base}} \text{ kA} \\Z_{base} &= \frac{V_{base}}{I_{base}} \Omega \\ \omega_{base} &= \omega_s = 2\pi f \text{ elect. rad/sec} \\ \omega_{m \text{ base}} &= \frac{2}{p}\omega_{base} \text{ mech. rad/sec} \\L_{base} &= \frac{Z_{base}}{\omega_{base}} \text{ H} \\\lambda_{base} &= \frac{V_{base}}{\omega_{base}} \text{ Wb-turn, } t_{base} = \frac{1}{\omega_{base}} \text{ s/rad}\end{aligned} \tag{44}$$

$$\begin{aligned}
 V_{dq0,base} &= \sqrt{2} V_{base} \text{ kV} \\
 S_{base} &= \frac{3}{2} V_{dq0,base} I_{dq0,base} \text{ MVA} \\
 I_{dq0,base} &= \frac{2}{3} \frac{S_{base}}{V_{dq0,base}} = \frac{2}{3} \frac{S_{base}}{\sqrt{2} V_{base}} = \frac{\sqrt{2} S_{base}}{3 V_{base}} = \sqrt{2} I_{base} \text{ kA} \\
 Z_{dq0,base} &= \frac{V_{dq0,base}}{I_{dq0,base}} \Omega \\
 L_{dq0,base} &= \frac{Z_{dq0,base}}{\omega_{base}} \text{ H} \\
 \lambda_{dq0,base} &= \frac{V_{dq0,base}}{\omega_{base}} \text{ Wb-turn}
 \end{aligned} \tag{45}$$

Base Quantities for Rotor Variables

$$\begin{aligned} S_{base} &= V_{fd,base} I_{fd,base} \\ I_{fd,base} &= \frac{I_{md}}{I_{sfd}} I_{dq0,base} \\ V_{fd,base} &= \frac{S_{base}}{I_{fd,base}} = \frac{3}{2} \frac{I_{sfd}}{I_{md}} V_{dq0,base} \\ \lambda_{fd,base} &= \frac{V_{fd,base}}{\omega_{base}} \\ Z_{fd,base} &= \frac{V_{fd,base}}{I_{fd,base}} \\ L_{fd,base} &= \frac{V_{fd,base}}{\omega_{base} I_{fd,base}} = \frac{Z_{fd,base}}{\omega_{base}} \end{aligned} \tag{46}$$

Let us define them for damper windings.

① *d*-axis winding

$$\begin{aligned} S_{base} &= V_{1d,base} I_{1d,base} \\ I_{1d,base} &= \frac{I_{md}}{I_{s1d}} I_{dq0,base} \\ V_{1d,base} &= \frac{S_{base}}{I_{1d,base}} = \frac{3}{2} \frac{I_{s1d}}{I_{md}} V_{dq0,base} \\ \lambda_{1d,base} &= \frac{V_{1d,base}}{\omega_{base}} \\ Z_{1d,base} &= \frac{V_{1d,base}}{I_{1d,base}} \\ L_{1d,base} &= \frac{V_{1d,base}}{\omega_{base} I_{1d,base}} = \frac{Z_{1d,base}}{\omega_{base}} \end{aligned} \tag{47}$$

2 q -axis winding

$$\begin{aligned} S_{base} &= V_{1q,base} I_{1q,base} \\ I_{1q,base} &= \frac{I_{mq}}{I_{s1q}} I_{dq0,base} \\ V_{1q,base} &= \frac{S_{base}}{I_{1q,base}} = \frac{3}{2} \frac{I_{s1q}}{I_{mq}} V_{dq0,base} \\ \lambda_{1q,base} &= \frac{V_{1q,base}}{\omega_{base}} \\ Z_{1q,base} &= \frac{V_{1q,base}}{I_{1q,base}} \\ L_{1q,base} &= \frac{V_{1q,base}}{\omega_{base} I_{1q,base}} = \frac{Z_{1q,base}}{\omega_{base}} \end{aligned} \tag{48}$$

$$\begin{aligned}
 S_{base} &= V_{2q,base} I_{2q,base} \\
 I_{2q,base} &= \frac{I_{mq}}{I_{s2q}} I_{dq0,base} \\
 V_{2q,base} &= \frac{S_{base}}{I_{2q,base}} = \frac{3}{2} \frac{I_{s2q}}{I_{mq}} V_{dq0,base} \\
 \lambda_{2q,base} &= \frac{V_{2q,base}}{\omega_{base}} \\
 Z_{2q,base} &= \frac{V_{2q,base}}{I_{2q,base}} \\
 L_{2q,base} &= \frac{V_{2q,base}}{\omega_{base} I_{2q,base}} = \frac{Z_{2q,base}}{\omega_{base}}
 \end{aligned} \tag{49}$$

Let us define the following.

$$\begin{aligned}
 V_d &= \frac{v_d}{V_{dq0,base}}, \quad V_q = \frac{v_q}{V_{dq0,base}}, \quad V_0 = \frac{v_0}{V_{dq0,base}} \\
 I_d &= \frac{i_d}{I_{dq0,base}}, \quad I_q = \frac{i_q}{I_{dq0,base}}, \quad I_0 = \frac{i_0}{I_{dq0,base}} \\
 V_{fd} &= \frac{v_{fd}}{V_{fd,base}}, \quad V_{1d} = \frac{v_{1d}}{V_{1d,base}}, \quad V_{1q} = \frac{v_{1q}}{V_{1q,base}}, \quad V_{2q} = \frac{v_{2q}}{V_{2q,base}} \\
 I_{fd} &= \frac{i_{fd}}{I_{fd,base}}, \quad I_{1d} = \frac{i_{1d}}{I_{1d,base}}, \quad I_{1q} = \frac{i_{1q}}{I_{1q,base}}, \quad I_{2q} = \frac{i_{2q}}{I_{2q,base}} \\
 \psi_d &= \frac{\lambda_d}{\lambda_{dq0,base}}, \quad \psi_q = \frac{\lambda_q}{\lambda_{dq0,base}} \\
 \psi_{fd} &= \frac{\lambda_{fd}}{\lambda_{fd,base}}, \quad \psi_{1d} = \frac{\lambda_{1d}}{\lambda_{1d,base}}, \quad \psi_{1q} = \frac{\lambda_{1q}}{\lambda_{1q,base}}, \quad \psi_{2q} = \frac{\lambda_{2q}}{\lambda_{2q,base}} \\
 R_s &= \frac{r_s}{Z_{dq0,base}} \\
 R_{fd} &= \frac{r_{fd}}{Z_{fd,base}}, \quad R_{1d} = \frac{r_{1d}}{Z_{1d,base}}, \quad R_{1q} = \frac{r_{1q}}{Z_{1q,base}}, \quad R_{2q} = \frac{r_{2q}}{Z_{2q,base}},
 \end{aligned} \tag{50}$$

Voltage Equations in per unit

The stator and rotor voltage equations given in equations (26)-(32) are converted to per unit form as follows:

$$V_d = -R_s I_d - \frac{\omega}{\omega_{base}} \psi_q + \frac{1}{\omega_{base}} \frac{d\psi_d}{dt} \quad (51)$$

$$V_q = -R_s I_q + \frac{\omega}{\omega_{base}} \psi_d + \frac{1}{\omega_{base}} \frac{d\psi_q}{dt} \quad (52)$$

$$V_0 = -R_s I_0 + \frac{1}{\omega_{base}} \frac{d\psi_0}{dt} \quad (53)$$

$$V_{fd} = R_{fd} I_{fd} + \frac{1}{\omega_{base}} \frac{d\psi_{fd}}{dt} \quad (54)$$

$$V_{1d} = R_{1d} I_{1d} + \frac{1}{\omega_{base}} \frac{d\psi_{1d}}{dt} \quad (55)$$

$$V_{1q} = R_{1q} I_{1q} + \frac{1}{\omega_{base}} \frac{d\psi_{1q}}{dt} \quad (56)$$

$$V_{2q} = R_{2q} I_{2q} + \frac{1}{\omega_{base}} \frac{d\psi_{2q}}{dt} \quad (57)$$

Instantaneous Power

Before converting it into per unit, let us substitute voltage equations given in (26)-(28) in (25).

$$\begin{aligned} s &= \frac{3}{2} \left\{ (-r_s i_d - \omega \lambda_q + \frac{d\lambda_d}{dt}) i_d + (-r_s i_q + \omega \lambda_d + \frac{d\lambda_q}{dt}) i_q + 2(-r_s i_0 + \frac{d\lambda_0}{dt}) i_0 \right\} \\ &= \left\{ \frac{3}{2} \left(\frac{d\lambda_d}{dt} i_d + \frac{d\lambda_q}{dt} i_q + \frac{d\lambda_0}{dt} i_0 \right) + \frac{3}{2} \omega (\lambda_d i_q - \lambda_q i_d) - \frac{3}{2} (r_s i_d^2 + r_s i_q^2 + 2r_s i_0^2) \right\} \end{aligned} \quad (59)$$

For a balanced system, v_0 and i_0 are zero.

$$s = \left\{ \underbrace{\frac{3}{2} \left(\frac{d\lambda_d}{dt} i_d + \frac{d\lambda_q}{dt} i_q \right)}_I + \underbrace{\frac{3}{2} \omega (\lambda_d i_q - \lambda_q i_d)}_{II} - \underbrace{\frac{3}{2} (r_s i_d^2 + r_s i_q^2)}_{III} \right\} \quad (60)$$

I = rate of change of stored magnetic energy in the stator windings

II = electrical power crossing the air gap

III = stator copper losses

The electrical torque T_e in N-m can be found

$$\begin{aligned} T_e &= \frac{P_e}{\omega_m} = \frac{P_e}{\frac{2}{p}\omega} = \frac{\frac{3}{2}\omega (\lambda_d i_q - \lambda_q i_d)}{\frac{2}{p}\omega} \\ T_e &= \frac{3}{2} \frac{P}{2} (\lambda_d i_q - \lambda_q i_d) \text{ N-m} \end{aligned} \quad (61)$$

To convert it into per unit, let us define the following.

$$\begin{aligned} T_{base} &= \frac{S_{base}}{\omega_{m,base}} = \frac{\frac{3}{2} V_{dq0,base} I_{dq0,base}}{\frac{2}{p}\omega_{base}} \\ &= \frac{3}{2} \frac{P}{2} \lambda_{dq0,base} I_{dq0,base} \end{aligned} \quad (62)$$

The electrical torque (T_e) in per unit is given by

$$T_e = \frac{\frac{3}{2} \frac{P}{2} (\lambda_d i_q - \lambda_q i_d)}{\frac{3}{2} \frac{P}{2} \lambda_{dq0,base} I_{dq0,base}}$$

$T_e = \psi_d I_q - \psi_q I_d$

(63)

In per unit calculations, the torque and power are the same.

Flux Linkage Equations in per unit

1 Flux linkage equations of windings in d -axis

$$\lambda_d = -(l_{md} + l_s)i_d + l_{sfd}i_{fd} + l_{s1d}i_{1d} \quad (64)$$

$$\lambda_{fd} = -\frac{3}{2}l_{sfd}i_d + l_{fdfd}i_{fd} + l_{fd1d}i_{1d} \quad (65)$$

$$\lambda_{1d} = -\frac{3}{2}l_{s1d}i_d + l_{fd1d}i_{fd} + l_{1d1d}i_{1d} \quad (66)$$

From (51),

$$i_d = l_d l_{dq0,base}; \quad i_{fd} = l_{fd} l_{fd,base}; \quad i_{1d} = l_{1d} l_{1d,base}$$

Equations (64) -(66) are divided by their respective bases to convert them into per unit form.

$$\frac{\lambda_d}{\lambda_{dq0,base}} = -\frac{(l_{md} + l_s)l_d l_{dq0,base}}{\lambda_{dq0,base}} + \frac{l_{sfd}l_{fd} l_{fd,base}}{\lambda_{dq0,base}} + \frac{l_{s1d}l_{1d} l_{1d,base}}{\lambda_{dq0,base}} \quad (67)$$

$$\frac{\lambda_{fd}}{\lambda_{fd,base}} = -\frac{3}{2} \frac{I_{sfd} I_d I_{dq0,base}}{\lambda_{fd,base}} + \frac{I_{fd} I_{fd} I_{fd,base}}{\lambda_{fd,base}} + \frac{I_{fd} I_d I_{1d,base}}{\lambda_{fd,base}} \quad (68)$$

$$\frac{\lambda_{1d}}{\lambda_{1d,base}} = -\frac{3}{2} \frac{I_{s1d} I_d I_{dq0,base}}{\lambda_{1d,base}} + \frac{I_{fd} I_d I_{fd,base}}{\lambda_{1d,base}} + \frac{I_{1d} I_d I_{1d,base}}{\lambda_{1d,base}} \quad (69)$$

From (46) - (48),

$$\lambda_{dq0,base} = \frac{V_{dq0,base}}{\omega_{base}}; \lambda_{fd,base} = \frac{V_{fd,base}}{\omega_{base}}; \lambda_{1d,base} = \frac{V_{1d,base}}{\omega_{base}}$$

By using the above terms, the equations (67) - (69) can be written as follows:

$$\psi_d = -\frac{\omega_{base}(I_{md} + I_{ls})I_d I_{dq0,base}}{V_{dq0,base}} + \frac{\omega_{base}I_{sfd}I_{fd}I_{fd,base}}{V_{dq0,base}} + \frac{\omega_{base}I_{s1d}I_{1d}I_{1d,base}}{V_{dq0,base}} \quad (70)$$

$$\psi_{fd} = -\frac{3}{2} \frac{\omega_{base} l_{sfd} l_d l_{dq0,base}}{V_{fd,base}} + \frac{\omega_{base} l_{fd} l_{fd,base}}{V_{fd,base}} + \frac{\omega_{base} l_{fd} l_{1d} l_{1d,base}}{V_{fd,base}} \quad (71)$$

$$\psi_{1d} = -\frac{3}{2} \frac{\omega_{base} l_{s1d} l_d l_{dq0,base}}{V_{1d,base}} + \frac{\omega_{base} l_{fd} l_{1d} l_{1d,base}}{V_{1d,base}} + \frac{\omega_{base} l_{1d} l_{1d,base}}{V_{1d,base}} \quad (72)$$

From (46) and (47),

$$l_{fd,base} = \frac{l_{md}}{l_{sfd}} l_{dq0,base}; \quad V_{fd,base} = \frac{3}{2} \frac{l_{sfd}}{l_{md}} V_{dq0,base}$$

$$l_{1d,base} = \frac{l_{md}}{l_{s1d}} l_{dq0,base}; \quad V_{1d,base} = \frac{3}{2} \frac{l_{s1d}}{l_{md}} V_{dq0,base}$$

By using the above terms, the equations (70) - (72) can be written as follows:

$$\psi_d = -\frac{\omega_{base}(I_{md} + I_{ls})I_d I_{dq0,base}}{V_{dq0,base}} + \frac{\omega_{base}I_{md}I_{fd}I_{dq0,base}}{V_{dq0,base}} + \frac{\omega_{base}I_{md}I_{1d}I_{dq0,base}}{V_{dq0,base}} \quad (73)$$

$$\psi_{fd} = -\frac{\omega_{base}I_{md}I_d I_{dq0,base}}{V_{dq0,base}} + \frac{\omega_{base}I_{fd}I_{fd}I_{fd,base}}{V_{fd,base}} + \frac{\omega_{base}I_{fd}I_{1d}I_{1d,base}}{V_{fd,base}} \quad (74)$$

$$\psi_{1d} = -\frac{\omega_{base}I_{md}I_d I_{dq0,base}}{V_{dq0,base}} + \frac{\omega_{base}I_{fd}I_{1d}I_{fd,base}}{V_{1d,base}} + \frac{\omega_{base}I_{1d}I_{1d}I_{1d,base}}{V_{1d,base}} \quad (75)$$

The mutual inductances have been made equal.

2 Flux linkage equations of windings in q -axis

After following the same steps used in d -axis,

$$\psi_q = -\frac{\omega_{base}(I_{mq} + I_{ls})I_q I_{dq0,base}}{V_{dq0,base}} + \frac{\omega_{base}I_{mq}I_{1q}I_{dq0,base}}{V_{dq0,base}} + \frac{\omega_{base}I_{mq}I_{2q}I_{dq0,base}}{V_{dq0,base}} \quad (76)$$

$$\psi_{1q} = -\frac{\omega_{base}I_{mq}I_q I_{dq0,base}}{V_{dq0,base}} + \frac{\omega_{base}I_{1q}I_q I_{1q,base}}{V_{1q,base}} + \frac{\omega_{base}I_{1q}I_{2q}I_{2q,base}}{V_{1q,base}} \quad (77)$$

$$\psi_{2q} = -\frac{\omega_{base}I_{mq}I_q I_{dq0,base}}{V_{dq0,base}} + \frac{\omega_{base}I_{1q}I_{2q}I_{1q,base}}{V_{2q,base}} + \frac{\omega_{base}I_{2q}I_{2q}I_{2q,base}}{V_{2q,base}} \quad (78)$$

Let us define the following parameters to simplify the equations (73) -(75) and (76) - (78).

$$\begin{aligned}
 X_{ls} &= \frac{x_{ls}}{Z_{dq0,base}} = \frac{\omega_{base} l_{ls}}{Z_{dq0,base}} = \frac{\omega_{base} l_{ls} l_{dq0,base}}{V_{dq0,base}} \\
 X_{md} &= \frac{x_{md}}{Z_{dq0,base}} = \frac{\omega_{base} l_{md}}{Z_{dq0,base}} = \frac{\omega_{base} l_{md} l_{dq0,base}}{V_{dq0,base}} \\
 X_{mq} &= \frac{x_{mq}}{Z_{dq0,base}} = \frac{\omega_{base} l_{mq}}{Z_{dq0,base}} = \frac{\omega_{base} l_{mq} l_{dq0,base}}{V_{dq0,base}} \\
 X_{fd} &= \frac{x_{fd} l_{fd}}{Z_{fd,base}} = \frac{\omega_{base} l_{fd} l_{fd}}{Z_{fd,base}} = \frac{\omega_{base} l_{fd} l_{fd} l_{fd,base}}{V_{fd,base}} \\
 X_{1d} &= \frac{x_{1d} l_{1d}}{Z_{1d,base}} = \frac{\omega_{base} l_{1d} l_{1d}}{Z_{1d,base}} = \frac{\omega_{base} l_{1d} l_{1d} l_{1d,base}}{V_{1d,base}} \\
 X_{1q} &= \frac{x_{1q} l_{1q}}{Z_{1q,base}} = \frac{\omega_{base} l_{1q} l_{1q}}{Z_{1q,base}} = \frac{\omega_{base} l_{1q} l_{1q} l_{1q,base}}{V_{1q,base}} \\
 X_{2q} &= \frac{x_{2q} l_{2q}}{Z_{2q,base}} = \frac{\omega_{base} l_{2q} l_{2q}}{Z_{2q,base}} = \frac{\omega_{base} l_{2q} l_{2q} l_{2q,base}}{V_{2q,base}}
 \end{aligned} \tag{79}$$

$$\begin{aligned}
 X_{fd1d} &= \frac{\omega_{base} l_{fd1d} l_{1d,base}}{V_{fd,base}} = \frac{\omega_{base} l_{fd1d}}{V_{fd,base}} \frac{l_{sfd}}{l_{s1d}} l_{fd,base} \\
 &= \frac{\omega_{base} l_{fd1d}}{Z_{fd,base}} \frac{l_{sfd}}{l_{s1d}} \\
 X_{1q2q} &= \frac{\omega_{base} l_{1q2q} l_{2q,base}}{V_{1q,base}} = \frac{\omega_{base} l_{1q2q}}{V_{1q,base}} \frac{l_{s1q}}{l_{s2q}} l_{1q,base} \\
 &= \frac{\omega_{base} l_{1q2q}}{Z_{1q,base}} \frac{l_{s1q}}{l_{s2q}}
 \end{aligned} \tag{80}$$

$$\begin{aligned}
 X_d &= X_{ls} + X_{md}, \quad X_q = X_{ls} + X_{mq}, \quad X_{lfd} = X_{fd} - X_{md} \\
 X_{l1d} &= X_{1d} - X_{md}, \quad X_{l1q} = X_{1q} - X_{mq}, \quad X_{l2q} = X_{2q} - X_{mq}
 \end{aligned} \tag{81}$$

By using (79), (80), (81) and defining $K_d = \frac{X_{fd1d}}{X_{md}}$ and $K_q = \frac{X_{1q2q}}{X_{mq}}$, the flux linkage equations can be written as follows:

$$\psi_d = X_d(-I_d) + X_{md}I_{fd} + X_{md}I_{1d} \quad (82)$$

$$\psi_{fd} = X_{md}(-I_d) + X_{fd}I_{fd} + K_d X_{md}I_{1d} \quad (83)$$

$$\psi_{1d} = X_{md}(-I_d) + K_d X_{md}I_{fd} + X_{1d}I_{1d} \quad (84)$$

$$\psi_q = X_q(-I_q) + X_{mq}I_{1q} + X_{mq}I_{2q} \quad (85)$$

$$\psi_{1q} = X_{mq}(-I_q) + X_{1q}I_{1q} + K_q X_{mq}I_{2q} \quad (86)$$

$$\psi_{2q} = X_{mq}(-I_q) + K_q X_{mq}I_{1q} + X_{2q}I_{2q} \quad (87)$$

If K_d and K_q are assumed to be unity,

① d -axis flux linkage equations

$$\psi_d = X_d(-I_d) + X_{md}I_{fd} + X_{md}I_{1d} \quad (88)$$

$$\psi_{fd} = X_{md}(-I_d) + X_{fd}I_{fd} + X_{md}I_{1d} \quad (89)$$

$$\psi_{1d} = X_{md}(-I_d) + X_{md}I_{fd} + X_{1d}I_{1d} \quad (90)$$

② q -axis flux linkage equations

$$\psi_q = X_q(-I_q) + X_{mq}I_{1q} + X_{mq}I_{2q} \quad (91)$$

$$\psi_{1q} = X_{mq}(-I_q) + X_{1q}I_{1q} + X_{mq}I_{2q} \quad (92)$$

$$\psi_{2q} = X_{mq}(-I_q) + X_{mq}I_{1q} + X_{2q}I_{2q} \quad (93)$$

Synchronous Machine Parameters

- Synchronous machine parameters are normally specified in terms of sub-transient and transient reactances, open circuit sub-transient and transient time constants.
- Those parameters need to be defined.
- ① Sub-transient reactance

$$X_d'' = X_{ls} + \frac{1}{\frac{1}{X_{md}} + \frac{1}{X_{lfd}} + \frac{1}{X_{l1d}}} \quad (94)$$

- This can be found by applying a voltage at stator terminals such that only I_d flows with all rotor circuits shorted.
- At $t = 0^+$, ψ_{fd} and ψ_{1d} will be zero.

Hence,

$$\psi_d = X_d(-I_d) + X_{md}I_{fd} + X_{md}I_{1d} \quad (95)$$

$$0 = X_{md}(-I_d) + X_{fd}I_{fd} + X_{md}I_{1d} \quad (96)$$

$$0 = X_{md}(-I_d) + X_{md}I_{fd} + X_{1d}I_{1d} \quad (97)$$

Solving (96) and (97) for I_{fd} and I_{1d} and considering (81),

$$I_{fd} = \frac{X_{md}X_{11d}}{X_{md}X_{lfd} + X_{md}X_{l1d} + X_{lfd}X_{l1d}} I_d \quad (98)$$

$$I_{1d} = \frac{X_{md}X_{lfd}}{X_{md}X_{lfd} + X_{md}X_{l1d} + X_{lfd}X_{l1d}} I_d \quad (99)$$

Substituting (98) and (99) in (95),

$$\psi_d = - \left(X_d - \frac{X_{md}^2(X_{lfd} + X_{l1d})}{X_{md}X_{lfd} + X_{md}X_{l1d} + X_{lfd}X_{l1d}} \right) I_d \quad (100)$$

Since $X_d = X_{ls} + X_{md}$,

$$\begin{aligned}\psi_d &= - \left(X_{ls} + \frac{X_{md} X_{lfd} X_{l1d}}{X_{md} X_{lfd} + X_{md} X_{l1d} + X_{lfd} X_{l1d}} \right) I_d \\ &= - \left(X_{ls} + \frac{1}{\frac{1}{X_{md}} + \frac{1}{X_{lfd}} + \frac{1}{X_{l1d}}} \right) I_d = -X_d'' I_d\end{aligned}\tag{101}$$

Similarly, the quadrature axis sub-transient reactance can be expressed as,

$$X_q'' = X_{ls} + \frac{1}{\frac{1}{X_{mq}} + \frac{1}{X_{l1q}} + \frac{1}{X_{l2q}}}\tag{102}$$

2 Transient reactance

$$X'_d = X_{ls} + \frac{1}{\frac{1}{X_{md}} + \frac{1}{X_{lfd}}} \quad (103)$$

It is found by the same approach followed for X''_d with an additional assumption that the damper winding transients settle down faster compared to the field winding transients. Hence $I_{1d} = 0$. With this assumption, by solving (95) and (96) and using (81),

$$\begin{aligned} \psi_d &= - \left(X_d - \frac{X_{md}^2}{X_{md} + X_{lfd}} \right) I_d = - \left(X_{ls} + \frac{X_{md} X_{lfd}}{X_{md} + X_{lfd}} \right) I_d \\ &= - \left(X_{ls} + \frac{1}{\frac{1}{X_{md}} + \frac{1}{X_{lfd}}} \right) I_d = -X'_d I_d \end{aligned} \quad (104)$$

Similarly, the quadrature axis transient reactance can be defined as

$$X'_q = X_{ls} + \frac{1}{\frac{1}{X_{mq}} + \frac{1}{X_{l1q}}} \quad (105)$$

③ Open circuit sub-transient time constant

- A voltage is applied to the field winding with stator terminals open so that $I_d = 0$.
- At $t = 0^+$, $\psi_{1d} = 0$.

Substituting these assumptions in (90) and (55),

$$I_{fd} = -\frac{X_{1d}}{X_{md}} I_{1d} \quad (106)$$

$$\frac{1}{\omega_{base}} \left(X_{md} \frac{dI_{fd}}{dt} + X_{1d} \frac{dI_{1d}}{dt} \right) + R_{1d} I_{1d} = V_{1d} = 0 \quad (107)$$

$$\frac{1}{\omega_{base}} \frac{dI_{fd}}{dt} = \left(-\frac{1}{\omega_{base}} \frac{X_{1d}}{X_{md}} \frac{dI_{1d}}{dt} - \frac{R_{1d}}{X_{md}} I_{1d} \right) \quad (108)$$

Substituting (89) in (54), we get

$$\frac{1}{\omega_{base}} \left(X_{fd} \frac{dI_{fd}}{dt} + X_{md} \frac{dI_{1d}}{dt} \right) + R_{fd} I_{fd} = V_{fd} \quad (109)$$

To get a first order differential equation in terms of I_{1d} with a forcing function V_{fd} , let us substitute (106) and (108) in (109).

$$\frac{1}{\omega_{base}} \left(-\frac{X_{fd}X_{1d}}{X_{md}} \frac{dI_{1d}}{dt} - \frac{X_{fd}R_{1d}}{X_{md}} I_{1d} + X_{md} \frac{dI_{1d}}{dt} \right) - \frac{R_{fd}X_{1d}}{X_{md}} I_{1d} = V_{fd} \quad (110)$$

On simplification, we get

$$\frac{1}{\omega_{base}} \left(\frac{X_{md}^2 - X_{fd}X_{1d}}{X_{fd}R_{1d} + X_{1d}R_{fd}} \right) \frac{dI_{1d}}{dt} - I_{1d} = \frac{X_{md}}{X_{fd}R_{1d} + X_{1d}R_{fd}} V_{fd} \quad (111)$$

In a practical generator, $R_{1d} \gg R_{fd}$. Therefore, $X_{1d}R_{fd}$ can be neglected. Simplifying (111), we get

$$-\frac{1}{\omega_{base}R_{1d}} \left(X_{l1d} + \frac{X_{md}X_{lfd}}{X_{md} + X_{lfd}} \right) \frac{dI_{1d}}{dt} - I_{1d} = \frac{X_{md}}{X_{fd}R_{1d}} V_{fd} \quad (112)$$

Hence, the open circuit d -axis time sub-transient time constant is

$$\begin{aligned} T''_{d0} &= \frac{1}{\omega_{base} R_{1d}} \left(X_{l1d} + \frac{X_{md} X_{lfd}}{X_{md} + X_{lfd}} \right) \\ &= \frac{1}{\omega_{base} R_{1d}} \left(X_{l1d} + \frac{1}{\frac{1}{X_{md}} + \frac{1}{X_{lfd}}} \right) \end{aligned} \quad (113)$$

Similarly, the open circuit q -axis time sub-transient time constant can be expressed as

$$T''_{q0} = \frac{1}{\omega_{base} R_{2q}} \left(X_{l2q} + \frac{1}{\frac{1}{X_{mq}} + \frac{1}{X_{l1q}}} \right) \quad (114)$$

4 Open circuit transient time constant

In addition to the assumptions made in calculating T''_{d0} , the current in the damper winding I_{1d} is zero. From (89) and (54), we get

$$\psi_{fd} = X_{fd} I_{fd} \quad (115)$$

$$\frac{X_{fd}}{\omega_{base} R_{fd}} \frac{dI_{fd}}{dt} + I_{fd} = \frac{V_{fd}}{R_{fd}} \quad (116)$$

Hence, the open circuit d -axis transient time constant, in seconds, is defined as

$$T'_{d0} = \frac{X_{fd}}{\omega_{base} R_{fd}} \quad (117)$$

Similarly, the open circuit q -axis transient time constant can be expressed as

$$T'_{q0} = \frac{X_{1q}}{\omega_{base} R_{1q}} \quad (118)$$

Let us also define the following new variables.

$$E'_q = \frac{X_{md}}{X_{fd}} \psi_{fd}, \quad E_{fd} = \frac{X_{md}}{R_{fd}} V_{fd}, \quad E'_d = -\frac{X_{mq}}{X_{1q}} \psi_{1q} \quad (119)$$

Our aim is to express the voltage equations and flux linkage equations using the sub-transient and transient reactances and open circuit time constants along with (119).

From (89) and (90),

$$\begin{bmatrix} I_{fd} \\ I_{1d} \end{bmatrix} = \begin{bmatrix} X_{fd} & X_{md} \\ X_{md} & X_{1d} \end{bmatrix}^{-1} \begin{bmatrix} \psi_{fd} \\ \psi_{1d} \end{bmatrix} + \begin{bmatrix} X_{fd} & X_{md} \\ X_{md} & X_{1d} \end{bmatrix}^{-1} \begin{bmatrix} X_{md} \\ X_{md} \end{bmatrix} I_d \quad (120)$$

Let $\Delta = X_{fd}X_{1d} - X_{md}^2 = X_{lfd}X_{md} + X_{l1d}X_{md} + X_{lfd}X_{l1d}$ Therefore,

$$\begin{aligned}
 I_{fd} &= \frac{1}{\Delta} (X_{1d}\psi_{fd} - X_{md}\psi_{1d}) + \frac{1}{\Delta} (X_{1d}X_{md} - X_{md}^2) I_d \\
 I_{1d} &= \frac{1}{\Delta} (-X_{md}\psi_{fd} + X_{fd}\psi_{1d}) + \frac{1}{\Delta} (X_{fd}X_{md} - X_{md}^2) I_d
 \end{aligned} \tag{121}$$

Equation (121) can be expressed using X_d'' , X_d' , X_d and (121) as given below.

$$\frac{1}{\Delta} X_{1d}\psi_{fd} = \frac{X_{fd}X_{1d}}{X_{md}\Delta} \frac{X_{md}}{X_{fd}} \psi_{fd} = \frac{1}{X_{md}} \left(1 + \frac{X_{md}^2}{\Delta} \right) \frac{X_{md}}{X_{fd}} \psi_{fd}$$

Since $\frac{X_{md}^2}{\Delta} = \frac{(X_d - X_d')(X_d' - X_d'')}{(X_d' - X_{ls})^2}$ and $E_q' = \frac{X_{md}}{X_{fd}} \psi_{fd}$,

$$\frac{1}{\Delta} X_{1d}\psi_{fd} = \frac{1}{X_{md}} \left(1 + \frac{(X_d - X_d')(X_d' - X_d'')}{(X_d' - X_{ls})^2} \right) E_q'$$

$$\frac{1}{\Delta} X_{md} \psi_{1d} = \frac{1}{X_{md}} \frac{X_{md}^2}{\Delta} \psi_{1d} = \frac{1}{X_{md}} \left(\frac{(X_d - X'_d)(X'_d - X''_d)}{(X'_d - X_{ls})^2} \right) \psi_{1d}$$

$$\frac{1}{\Delta} (X_{1d} X_{md} - X_{md}^2) I_d = \frac{1}{X_{lfd}} \frac{X_{lfd} X_{l1d} X_{md}}{\Delta}$$

Since $\frac{1}{X_{lfd}} = \frac{(X'_d - X_{ls})}{(X_d - X'_d)} X_{md}$ and $\frac{X_{lfd} X_{l1d} X_{md}}{\Delta} = X''_d - X_{ls}$,

$$\frac{1}{\Delta} (X_{1d} X_{md} - X_{md}^2) I_d = \frac{1}{X_{md}} \left(\frac{(X_d - X'_d)(X''_d - X_{ls})}{(X'_d - X_{ls})} \right) I_d$$

$$\frac{1}{\Delta} X_{md} \psi_{fd} = \frac{X_{fd}}{\Delta} \frac{X_{md}}{X_{fd}} \psi_{fd}$$

Since $\frac{X_{fd}}{\Delta} = \frac{(X'_d - X''_d)}{(X'_d - X_{ls})^2}$ and $E'_q = \frac{X_{md}}{X_{fd}} \psi_{fd}$,

$$\frac{1}{\Delta} X_{md} \psi_{fd} = \frac{(X'_d - X''_d)}{(X'_d - X_{ls})^2} E'_q$$

$$\frac{X_{fd}}{\Delta} \psi_{1d} = \frac{(X'_d - X''_d)}{(X'_d - X_{ls})^2} \psi_{1d}$$

$$\frac{1}{\Delta} (X_{fd} X_{md} - X_{md}^2) I_d = \frac{X_{lfd} X_{md}}{\Delta} I_d = \frac{(X'_d - X''_d)}{(X'_d - X_{ls})} I_d$$

By using the above terms, the equation (121) can be written as

$$\begin{aligned}
 I_{fd} &= \frac{1}{X_{md}} \left(E'_q + \frac{(X_d - X'_d)(X'_d - X''_d)}{(X'_d - X_{ls})^2} \left(E'_q + \frac{(X'_d - X_{ls})(X''_d - X_{ls})}{(X'_d - X''_d)} I_d + \psi_{1d} \right) \right) \\
 &= \frac{1}{X_{md}} (E'_q + (X_d - X'_d)(I_d - I_{1d}))
 \end{aligned} \tag{122}$$

$$I_{1d} = \frac{(X'_d - X''_d)}{(X'_d - X_{ls})^2} (-E'_q + \psi_{1d} + I_d(X'_d - X_{ls})) \tag{123}$$

Substituting (122) and (123) in (88),

$$\begin{aligned}
 \psi_d &= X_d(-I_d) + X_{md}I_{fd} + X_{md}I_{1d} \\
 &= E'_q - X'_d I_d + (X'_d - X_{ls})I_{1d} \\
 &= -X''_d I_d + \frac{(X''_d - X_{ls})}{(X'_d - X_{ls})} E'_q + \frac{(X'_d - X''_d)}{(X'_d - X_{ls})} \psi_{1d}
 \end{aligned} \tag{124}$$

Similarly, the q -axis flux linkage and currents can be expressed as

$$\psi_q = -X_q'' I_q - \frac{(X_q'' - X_{ls})}{(X_q' - X_{ls})} E_d' + \frac{(X_q' - X_q'')}{(X_q' - X_{ls})} \psi_{2q} \quad (125)$$

$$I_{1q} = \frac{1}{X_{mq}} (-E_d' + (X_q - X_q')(I_q - I_{2q})) \quad (126)$$

$$I_{2q} = \frac{(X_q' - X_q'')}{(X_q' - X_{ls})^2} (E_d' + \psi_{2q} + I_q(X_q' - X_{ls})) \quad (127)$$

$$T''_{d0} = \frac{1}{\omega_{base} R_{1d}} \left(X_{l1d} + \frac{X_{md} X_{lfd}}{X_{md} + X_{lfd}} \right) = \frac{1}{\omega_{base} R_{1d}} \left(\frac{X_{l1d} X_{md} + X_{l1d} X_{lfd} + X_{md} X_{lfd}}{X_{fd}} \right)$$

$$= \frac{1}{\omega_{base} R_{1d}} \left(\frac{\Delta}{X_{fd}} \right) = \frac{1}{\omega_{base} R_{1d}} \left(\frac{(X'_d - X_{ls})^2}{(X'_d - X''_d)} \right)$$

Similarly,

$$T''_{q0} = \frac{1}{\omega_{base} R_{2q}} \left(\frac{(X'_q - X_{ls})^2}{(X'_q - X''_q)} \right)$$

By substituting the equations (122) - (127) in the voltage equations given in (54) - (57), we get

$$\frac{1}{\omega_{base}} \frac{d\psi_d}{dt} = V_d + R_s I_d + \frac{\omega}{\omega_{base}} \psi_q \quad (128)$$

$$\frac{1}{\omega_{base}} \frac{d\psi_q}{dt} = V_q + R_s I_q - \frac{\omega}{\omega_{base}} \psi_d \quad (129)$$

$$\frac{1}{\omega_{base}} \frac{d\psi_0}{dt} = V_0 + R_s I_0 \quad (130)$$

$$T'_{d0} \frac{dE'_q}{dt} = -E'_q - (X_d - X'_d)[I_d - \frac{(X'_d - X''_d)}{(X'_d - X_{ls})^2}(-E'_q + (X'_d - X_{ls})I_d + \psi_{1d})] + E_{fd} \quad (131)$$

$$T''_{d0} \frac{d\psi_{1d}}{dt} = E'_q - (X'_d - X_{ls})I_d - \psi_{1d} \quad (132)$$

$$T'_{q0} \frac{dE'_d}{dt} = -E'_d + (X_q - X'_q) \left(I_q - \frac{(X'_q - X''_q)}{(X'_q - X_{ls})^2} (E'_d + (X'_q - X_{ls})I_q + \psi_{2q}) \right) \quad (133)$$

$$T''_{q0} \frac{d\psi_{2q}}{dt} = -E'_d - (X'_q - X_{ls})I_q - \psi_{2q} \quad (134)$$

$$\psi_d = -X''_d I_d + \frac{(X''_d - X_{ls})}{(X'_d - X_{ls})} E'_q + \frac{(X'_d - X''_d)}{(X'_d - X_{ls})} \psi_{1d} \quad (135)$$

$$\psi_q = -X''_q I_q - \frac{(X''_q - X_{ls})}{(X'_q - X_{ls})} E'_d + \frac{(X'_q - X''_q)}{(X'_q - X_{ls})} \psi_{2q} \quad (136)$$

Apart from the above equations, the swing equation also needs to be considered.

$$\frac{d\delta}{dt} = \omega - \omega_s \quad (137)$$

$$\frac{2H}{\omega_s} \frac{d\omega}{dt} = T_m - T_e - D(\omega - \omega_{base}) \quad (138)$$

where $T_e = \psi_d I_q - \psi_q I_d$

Example 1

A 555 MVA, 24 kV, 0.9 pf, 60 Hz, 3 phase, 2 pole synchronous generator has the following inductances and resistances associated with the stator and rotor field windings: (P. Kundur Example 3.1)

$$l_{aa} = 3.2758 + 0.0458 \cos(2\theta) \text{ mH}$$

$$l_{ab} = -1.6379 - 0.0458 \cos(2\theta + 60^\circ) \text{ mH}$$

$$l_{ls} = 0.4129 \text{ mH}$$

$$l_{afd} = 40 \cos \theta \text{ mH}; \quad l_{fd} = 576.92 \text{ mH}$$

$$r_s = 0.0031 \, \Omega; \quad r_{fd} = 0.0715 \, \Omega$$

- 1 Determine l_d and l_q in Henrys.
- 2 Determine x_{md} and x_{mq} in Ohms.
- 3 Determine the per unit values all the parameters in $dq0$ frame.

Example 1 (contd.)

- ① We know that

$$I_d = \frac{3}{2}(I_{aa0} + I_{aap}); \quad I_q = \frac{3}{2}(I_{aa0} - I_{aap})$$

(refer to slide 28).

$$I_d = \frac{3}{2}(3.2758 + 0.0458) = 4.9824 \text{ mH}$$

$$I_q = \frac{3}{2}(3.2758 - 0.0458) = 4.845 \text{ mH}$$

Example 1 (contd.)

2

$$x_{md} = x_d - x_{ls} \quad x_{mq} = x_q - x_{ls}$$

(refer to slide 49 and equation (81)) Let us first find inductances

$$l_{md} = l_d - l_{ls} = 4.9824 - 0.4129 = 4.5695 \text{ mH}$$

$$l_{mq} = l_q - l_{ls} = 4.845 - 0.4129 = 4.4321 \text{ mH}$$

$$x_{md} = \omega_{base} l_{md} = 2 \times \pi \times 60 \times 4.5695 = 1.7227 \Omega$$

$$x_{mq} = \omega_{base} l_{mq} = 2 \times \pi \times 60 \times 4.4321 = 1.6709 \Omega$$

Example 1 (contd.)

- ③ Let us find the base quantities (refer to slides 32, 33, & 34).

$$V_{base} = \frac{24}{\sqrt{3}} = 13.8564 \text{ kV} \quad S_{base} = 555 \text{ MVA}$$

$$I_{base} = \frac{S_{base}}{3V_{base}} = \frac{555}{3 \times 13.8564} = 13.3512 \text{ kA}$$

$$V_{dq0,base} = \sqrt{2}V_{base} = \sqrt{2} \times 13.8564 = 19.5959 \text{ kV}$$

$$I_{dq0,base} = \sqrt{2}I_{base} = 18.8814 \text{ kA}$$

$$Z_{dq0,base} = \frac{V_{dq0,base}}{I_{dq0,base}} = \frac{19.56}{18.8814} = 1.0378 \Omega$$

$$L_{dq0,base} = \frac{Z_{dq0,base}}{\omega_{base}} = \frac{1.0378}{2 \times \pi \times 60} = 2.753 \text{ mH}$$

Example 1 (contd.)

$$I_{fd,base} = \frac{I_{md}}{I_{sfd}} I_{dq0,base} = \frac{4.5695}{40} \times 18.8814 = 2.158 \text{ kA}$$

$$(I_{sfd} = I_{afd}).$$

$$V_{fd,base} = \frac{S_{base}}{I_{fd,base}} = \frac{3 I_{md}}{2 I_{sfd}} V_{dq0,base} = 257.183 \text{ kV}$$

$$Z_{fd,base} = \frac{V_{fd,base}}{I_{fd,base}} = 119.18 \Omega$$

$$L_{fd,base} = \frac{Z_{fd,base}}{\omega_{base}} = 316.12 \text{ mH}$$

Example 1 (contd.)

The per unit values are

$$X_{md} = \frac{1.7227}{1.0378} = 1.66 \text{ p.u.}$$

$$X_{mq} = \frac{1.6709}{1.0378} = 1.61 \text{ p.u.}$$

$$L_{md} = \frac{4.5695}{2.753} = 1.66 \text{ p.u.}$$

$$L_{mq} = \frac{4.4321}{2.753} = 1.61 \text{ p.u.}$$

In the per unit system, $L = X$.

Example 1 (contd.)

$$X_{fd} = L_{fd} = \frac{I_{fd}}{L_{fd,base}} = \frac{576.92}{316.12} = 1.825 \text{ p.u.}$$

$$R_s = \frac{0.0031}{1.0378} = 0.003 \text{ p.u.}$$

$$R_{fd} = \frac{0.0715}{119.18} = 0.0006 \text{ p.u.}$$

Steady State Analysis

- ① In the steady state, the rotor rotates at the synchronous speed ($\omega = \omega_{base}$).
- ② Damper winding currents (I_{1d}, I_{1q}, I_{2q}) are zero.
- ③ In steady state, all the differential components vanish.
- ④ In steady state, the zero sequence component is zero.

In steady state, the equations (128) - (137) become,

$$V_d = -R_s I_d - \psi_q \quad (139)$$

$$V_q = -R_s I_q + \psi_d \quad (140)$$

$$E_{fd} = E'_q + (X_d - X'_d) I_d \quad (141)$$

$$\psi_{1d} = E'_q - (X'_d - X_{ls}) I_d \quad (142)$$

$$E'_d = (X_q - X'_q) I_q \quad (143)$$

$$\psi_{2q} = -E'_d - (X'_q - X_{ls}) I_q \quad (144)$$

The d -axis flux linkage equations given in (88) - (90) in the steady state are

$$\psi_d = X_d(-I_d) + X_{md} I_{fd} \quad (145)$$

$$\psi_{fd} = X_{md}(-I_d) + X_{fd} I_{fd} \quad (146)$$

$$\psi_{1d} = X_{md}(-I_d) + X_{md} I_{fd} \quad (147)$$

The q -axis flux linkage equations given in (91) - (93) in the steady state are

$$\psi_q = X_q(-I_q) \quad (148)$$

$$\psi_{1q} = X_{mq}(-I_q) \quad (149)$$

$$\psi_{2q} = X_{mq}(-I_q) \quad (150)$$

Substituting I_{fd} from (146) in (145), we get

$$\begin{aligned} \psi_d &= X_d(-I_d) + X_{md} \left(\frac{\psi_{fd} + X_{md} I_d}{X_{fd}} \right) \\ &= -I_d \left(X_d - \frac{X_{md}^2}{X_{fd}} \right) + \frac{X_{md}}{X_{fd}} \psi_{fd} \\ &= -I_d X'_d + E'_q \end{aligned} \quad (151)$$

From (144) and (150),

$$\begin{aligned} -X_{mq}I_q &= -E'_d - (X'_q - X_{ls})I_q \\ (X_{mq} + X_{ls})(-I_q) &= -E'_d - X'_qI_q \\ X_q(-I_q) &= -E'_d - X'_qI_q \\ \psi_q &= -E'_d - X'_qI_q \end{aligned} \tag{152}$$

Substituting (151) and (152) in (139) and (140),

$$V_d = -R_s I_d + X'_q I_q + E'_d \tag{153}$$

$$V_q = -R_s I_q - X'_d I_d + E'_q \tag{154}$$

Let the three phase terminal voltage in per unit be

$$\begin{aligned}v_{ta} &= V_m \cos(\omega t + \alpha) \\v_{tb} &= V_m \cos(\omega t + \alpha - 120^\circ) \\v_{tc} &= V_m \cos(\omega t + \alpha + 120^\circ)\end{aligned}\tag{155}$$

Applying the Park's transformation, we get

$$\begin{aligned}V_d &= V_m \cos(\omega t + \alpha - \theta) \\V_q &= V_m \sin(\omega t + \alpha - \theta)\end{aligned}\tag{156}$$

θ is the angle between d -axis and the stationary axis a . Let

$$\theta = \omega t + \theta_0$$


where θ_0 is rotor position at $t = 0$.

In per unit system, peak value and RMS value are the same.

$$\begin{aligned}V_d &= V_t \cos(\alpha - \theta_0) \\V_q &= V_t \sin(\alpha - \theta_0)\end{aligned}\tag{157}$$

Though V_d and V_q are scalar quantities, they can be represented as phasors due to their trigonometric relations.

$$V_t \angle \alpha - \theta_0 = V_d + jV_q\tag{158}$$



Let us define δ which is the angle between q -axis and V_t .

$$\delta = 90^\circ - (\alpha - \theta_0)$$

$$V_d + jV_q = V_t(\sin \delta + j \cos \delta) = \overline{V_t} \quad (159)$$

Similarly, the stator current I_t lagging V_t by ϕ can also be expressed as

$$I_d + jI_q = I_t(\sin(\delta + \phi) + j \cos(\delta + \phi)) = \overline{I_t} \quad (160)$$

Substituting (153) and (154) in (159), we get

$$\overline{V_t} = -R_s I_d + X'_q I_q + E'_d + j(-R_s I_q - X'_d I_d + E'_q) \quad (161)$$

Rearranging (161),

$$\begin{aligned}
 \overline{V}_t &= -R_s I_d + X'_q I_q + E'_d + j(-R_s I_q - X'_d I_d + E'_q) \\
 &= -R_s(I_d + jI_q) - jX_q(I_d + jI_q) + jX_q(I_d + jI_q) + X'_q I_q + E'_d + j(-X'_d I_d + E'_q) \\
 &= -(R_s + jX_q)\overline{I}_t + E'_d - (X_q - X'_q)I_q + j((X_q - X'_d)I_d + E'_q + X_d I_d - X_d I_d) \\
 &= -(R_s + jX_q)\overline{I}_t + E'_d - (X_q - X'_q)I_q + j((X_q - X_d)I_d + (X_d - X'_d)I_d + E'_q)
 \end{aligned}$$

From (143), $E'_d - (X_q - X'_q)I_q = 0$. From (141), $E_{fd} = E'_q + (X_d - X'_d)I_d$.

$$\overline{V}_t = -(R_s + jX_q)\overline{I}_t + j((X_q - X_d)I_d + E_{fd}) \quad (162)$$

Since $E_{fd} = \frac{X_{md}}{R_{fd}} V_{fd} = X_{md} I_{fd}$,

$$j((X_q - X_d)I_d + X_{md} I_{fd}) = \overline{V}_t + (R_s + jX_q)\overline{I}_t \quad (163)$$

Let the internal voltage of the generator be $E_q = (X_q - X_d)I_d + X_{md}I_{fd}$.

$$\begin{aligned} jE_q &= \overline{V}_t + (R_s + jX_q)\overline{I}_t \\ \overline{E}_q &= \overline{V}_t + (R_s + jX_q)\overline{I}_t \end{aligned} \quad (164)$$

$\overline{E}_q$ is defined as the internal voltage behind the synchronous reactance X_q . Equation (164) can be represented as




Figure: Equivalent circuit of steady state synchronous generator




Figure: Phasor diagram

Under no-load or open-circuit conditions, $I_d = I_q = 0$. From (143), (140), (141), (143), (145), and (148) we get

$$V_q = E_q = E'_q = E_{fd} = V_t = \psi_d = X_{md} I_{fd} \quad (165)$$

$$V_d = E'_d = \psi_q = 0 \quad (166)$$

Therefore

$$\overline{E}_q = jX_{md} I_{fd} \quad (167)$$

The terminal voltage

$$\overline{V}_t = V_d + jV_q = jV_q = jX_{md} I_{fd} \quad (168)$$

Steady state - No Saliency

If saliency is neglected,

$$X_d = X_q = X_s$$

where X_s is the synchronous reactance. Therefore,

$$\overline{E}_q = \overline{V}_t + (R_s + jX_s)\overline{I}_t \quad (169)$$

with $X_d = X_q$, the magnitude of E_q is

$$E_q = X_{md} I_{fd} \quad (170)$$




Figure: Steady state equivalent circuit with saliency neglected

Active and Reactive Power

The terminal complex power is

$$\begin{aligned} S &= \overline{V_t} \overline{I_t}^* \\ &= (V_d + jV_q)(I_d - jI_q) \\ &= (V_d I_d + V_q I_q) + j(V_q I_d - V_d I_q) \end{aligned}$$

$$P_t = V_d I_d + V_q I_q \quad (171)$$

$$Q_t = V_q I_d - V_d I_q \quad (172)$$

The steady state torque is given by

$$T_e = \psi_d I_q - \psi_q I_d$$

From (139) and (140)

$$\begin{aligned} T_e &= (V_q + R_s I_q) I_q + (V_d + R_s I_d) I_d \\ &= V_d I_d + V_q I_q + (I_d^2 + I_q^2) R_s \\ &= P_t + I_t^2 R_s = \text{Real}(\overline{E_q} \overline{I_t}^*) \end{aligned} \quad (173)$$


Steady state values - Procedure

For stability studies, it is necessary to find the initial steady-state values.

- 1 Normally, P_t , Q_t and V_t are specified. From the terminal conditions,

$$I_t = \frac{\sqrt{P_t^2 + Q_t^2}}{V_t}, \quad \phi = \cos^{-1} \left(\frac{P_t}{V_t I_t} \right)$$
$$\overline{E}_q = V_t \angle 0^\circ + I_t \angle -\phi (R_s + jX_q) \quad (174)$$

- 2 Find δ .



$$\delta = \tan^{-1} \left(\frac{I_t X_q \cos \phi - I_t R_s \sin \phi}{V_t + I_t R_s \cos \phi + I_t X_q \sin \phi} \right) \quad (175)$$

Steady state values - Procedure (contd.)

- ③ With δ known, the dq components of stator voltage and current are given by

$$V_d = V_t \sin \delta \quad (176)$$

$$V_q = V_t \cos \delta \quad (177)$$

$$I_d = I_t \sin(\delta + \phi) \quad (178)$$

$$I_q = I_t \cos(\delta + \phi) \quad (179)$$

Steady state values - Procedure (contd.)

- 4 The remaining machine quantities are computed as follows:

$$\psi_d = V_q + R_s I_q$$

$$\psi_q = -(V_d + R_s I_d)$$

$$I_{fd} = \frac{\psi_d + X_d I_d}{X_{md}}$$

$$E_{fd} = I_{fd} R_{fd}$$

$$\psi_{fd} = X_{md}(-I_d) + X_{fd} I_{fd}$$

$$\psi_{1d} = X_{md}(I_{fd} - I_d)$$

$$\psi_{1q} = \psi_{2q} = -X_{mq} I_q$$

$$T_e = P_t + I_t^2 R_s$$

Example 2

Consider a synchronous machine serving a load with

$$\overline{V_t} = 1.0 \angle 10^\circ \quad \overline{I_t} = 0.5 \angle -20^\circ$$

It has $X_d = 1.2$, $X_q = 1.0$, $X_{md} = 1.1$, $X'_d = 0.232$ and $R_s = 0$.

Find δ , V_d , V_q , I_d , I_q , ψ_d , ψ_q , E_q , E_{fd} , T_e , P_t .

① Let us find δ .

$$\delta = \tan^{-1} \left(\frac{I_t X_q \cos \phi - I_t R_s \sin \phi}{V_t + I_t R_s \cos \phi + I_t X_q \sin \phi} \right) = \tan^{-1} \left(\frac{0.5 \times 1 \times \sqrt{3}/2}{1 + 0.5 \times 1 \times 1/2} \right)$$

$$\delta = 19.1066^\circ$$

Example 2 (contd.)

2

$$V_d = V_t \sin \delta = 1 \times \sin(19.1^\circ) = 0.3273$$

$$V_q = V_t \cos \delta = 1 \times \cos(19.1^\circ) = 0.9449$$

$$I_d = I_t \sin(\delta + \phi) = 0.5 \times \sin(19.1^\circ + 30^\circ) = 0.3780$$

$$I_q = I_t \cos(\delta + \phi) = 0.5 \times \cos(19.1^\circ + 30^\circ) = 0.3273$$

3

$$\psi_d = V_q + R_s I_q = 0.9449$$

$$\psi_q = -(V_d + R_s I_d) = -0.3273$$

$$I_{fd} = \frac{\psi_d + X_d I_d}{X_{md}} = \frac{0.9449 + 1.2 \times 0.3780}{1.1} = 1.2713$$

$$E_q = (X_q - X_d) I_d + X_{md} I_{fd} = (1 - 1.2) \times 0.3780 + 1.1 \times 1.2161 = 1.3229$$

Example 2 (contd.)

4

$$T_e = \psi_d I_q - \psi_q I_d = 0.9449 \times 0.3273 + 0.3273 \times 0.3780 = 0.4330$$

$$P_t = \text{Real}(\overline{V_t} \overline{I_t}^*) = \text{Real}(1.0/\underline{10^\circ} \times 0.5/\underline{20^\circ}) = 0.4330$$

$$T_e = P_t + I_t^2 R_s$$

Since $R_s = 0$, $T_e = P_t$.

Saturation Effect

Assumptions

- 1 Saturation does not affect leakage inductances as the path of leakage fluxes is mainly air.
- 2 Saturation affects only mutual inductances.
- 3 The effect of saturation on mutual inductances can be computed through the open circuit characteristics of machines.
- 4 There is no saturation effect on mutual coupling between d and q axes.

Therefore, the effects of saturation may be represented as

$$X_{md,sat} = K_{sd} X_{md,unsat}, \quad X_{mq,sat} = K_{sq} X_{mq,unsat}$$

where K_{sd} and K_{sq} are the degrees of saturation in the d and q -axis, respectively.

At no load, $I_d = I_q = 0$. From (145) and (148),

$$\psi_d = X_{md} I_{fd}, \quad \psi_q = 0 \quad (180)$$

From stator voltage equations,

$$V_t = \sqrt{V_d^2 + V_q^2} = \psi_d \quad (181)$$

It shows that in per unit the terminal voltage and the stator flux linkage are the same.

At no load, the stator flux linkage is

$$\psi_t = \sqrt{\psi_d^2 + \psi_q^2} = \psi_d = V_t \quad (182)$$




Figure: Open circuit characteristics of a synchronous generator

if we neglect R_a ,

$$K I_{f,sc} = 1.0 X_{s,unsat} \quad (183)$$

where K is the slope of the air gap line.

To produce 1.0 p.u. terminal voltage,

$$K I_{f,ag} = 1.0 \quad (184)$$

Hence,

$$X_{s,unsat} = \frac{I_{f,sc}}{I_{f,ag}} \quad (185)$$

Similarly, the saturated synchronous reactance is

$$X_{s,sat} = \frac{I_{f,sc}}{I_{f,nl}} \quad (186)$$

Let us define the short circuit ratio (SCR).

$$\text{SCR} = \frac{I_{f,nl}}{I_{f,sc}} = \frac{1}{X_{s,sat}} \quad (187)$$




Figure: Open circuit characteristics

$$X_{md,unsat} = \frac{\psi_t}{I_{f,ag}} = \frac{\psi_{t,ag}}{I_{f,nl}} \quad (188)$$

$$X_{md,sat} = \frac{\psi_t}{I_{f,nl}} \quad (189)$$

From (188) and (189),

$$X_{md,sat} = \frac{\psi_t}{\psi_{t,ag}} X_{md,unsat} = \frac{\psi_t}{\psi_t + \psi_J} X_{md,unsat} \quad (190)$$

If $\psi_t \leq \psi_{lin}$,

$$\psi_J = 0; \quad X_{md,sat} = X_{md,unsat}$$

If $\psi_t > \psi_{lin}$,

$$\psi_J = A_{sat} e^{B_{sat}(\psi_t - \psi_{lin})}$$

① Cylindrical pole rotor

$$X_{mq,sat} = X_{md,sat}$$

- ② Salient pole rotor: The effect of saturation on q -axis is neglected as the air gap is more along q -axis.

It can be extended to loaded conditions as given below.

$$\begin{aligned}\psi_d &= (X_{ls} + X_{md})(-I_d) + X_{md}I_{fd} + X_{md}I_{1d} = -X_{ls}I_d + \psi_{md} \\ \psi_q &= (X_{ls} + X_{mq})(-I_q) + X_{mq}I_{1q} + X_{mq}I_{2q} = -X_{ls}I_q + \psi_{mq}\end{aligned}\quad (191)$$

Substituting the stator voltage equations in steady state given in (139) and (140) in (191),

$$\begin{aligned}\psi_{md} &= \psi_d + X_{ls}I_d = V_q + R_sI_q + X_{ls}I_d \\ \psi_{mq} &= \psi_q + X_{ls}I_q = -V_d - R_sI_d + X_{ls}I_q\end{aligned}\quad (192)$$

$$\psi_{md} + j\psi_{mq} = V_q + R_sI_q + X_{ls}I_d + j(-V_d - R_sI_d + X_{ls}I_q)\quad (193)$$

Let E_l be the voltage behind leakage reactance.

$$E_l = V_t + (R_s + jX_{ls})I_t \quad (194)$$

From (193) and (194),

$$\psi_t = \sqrt{\psi_{md}^2 + \psi_{mq}^2} = |E_l| \quad (195)$$

- ψ_t computed from (195) is used to calculate $X_{md,sat}$ and $X_{mq,sat}$.
- They have to be used for calculating sub-transient and transient reactances and time constants.